



**NOTES**

- 1. WHEN REGULATOR NOT FITTED STRAP INST. TMS 15-21-27.
- WHEN REGULATOR NOT FITTED A 150 OHM RESISTOR IS CONNECTED BETWEEN INST TMS 23 & 24 TO REDUCE RECEPTION & SIDETONE LEVELS.
- 2. BELL FITTED WHEN REQUIRED.

207568/SW